


# Eazy Angle

## Contact Angle Measurement

Easy To Use, Easy To Analyse



### Specification

Manual Contact Angle Measurement  
Platform Size 380X390X400(mm)  
MAX. Movement Distance 670(mm)  
Frame Rate 30 Frame/Sec

### System Requirement

USB 1.0/1.1 Interface.  
Pentium II 450 Or above CPU.  
256MB RAM.  
CD-ROM.  
OS: WINDOWS 98/ME/2000/XP.